


CEMVS-OD-J

5 November 2015

MEMORANDUM FOR CEMVS-OD-T/Neher

SUBJECT: Annual Boundary Report; Clarence Cannon Dam and Mark Twain Lake

1. Attached is the annual boundary report for Mark Twain Lake for FY15. The report includes flowage easements and corrective action.
2. If you have questions, please contact Allen Mehrer at (573) 735-4097.



SANDRA J. SPENCE  
Operations Manager

**Annual Boundary Report; Clarence Cannon Dam and Mark Twain Lake, FY 15**

1. Approximately 80 miles of perimeter boundary line at Mark Twain Lake was inspected and maintained by Project staff during FY 2015. The following is the list of perimeter boundary line inspected and maintained:

Boundary Line Inspection/Maintenance- FY 2015 :

Perimeter boundary in T54N, R8W, Sections 3, 4, 9, 10, 11, 12, 16, 18, 19, 21, 28, 29, 30, 31, 32, 33 .

Perimeter boundary in T53N, R8W, Sections 4, 6, 7, 8, 9, 16, 17, 18

Perimeter boundary in T54N, R9W, Sections 4, 5, 6, 7, 8, 9, 10, 12, 13, 14, 15, 16, 20, 21, 22, 23, 28, 29, 30, 32, 33, 36.

Perimeter boundary in T54N, R10W, Section 1.

2. The following is a list of identified encroachments on fee title lands encountered during FY 2015.

**2015 to Date – Identified Encroachments**

ENCROACHMENT/ TRESPASS	LOCATION	ACTION
ATV Trail	Township 54N, Range 9W, Section 7 N 39 28.952 W 91 57.681 Tawney	Sent letter of violation. Verbal contact with landowner.
ATV Trail	Township 54N, Range 9W, Section 6 N 39 29.488 W 91 57.033 Leinweber	Sent letter of violation. Verbal contact with landowner.
ATV Trail	Township 54N, Range 9W, Section 6 N 39 29.346 W 91 57.433 Jurgesmeyer	Sent letter of violation. Verbal contact with landowner.
ATV Trail	Township 53N, Range 8W, Section 4 N 39 24.211 W 91 48.196 Roseman	Sent letter of violation. Verbal contact with landowner.
ATV Trail	Township 53N, Range 8W, Section 18 N 39 22.774 W 91 49.860	Verbal contact made with landowner. Physical closure will be necessary.

**Annual Boundary Report; Clarence Cannon Dam and Mark Twain Lake, FY 15**

**2015 to Date – Identified Encroachments (cont.)**

<b>ENCROACHMENT/ TRESPASS</b>	<b>LOCATION</b>	<b>ACTION</b>
Mowing Project lands	Township 55N, Range 7W, Section 34 Schuette	Sent letter of violation. Notice was received.
Mowing Project lands	Township 55N, Range 7W, Section 34 Schneider	Sent letter of violation. Notice was received. Landowner issued boundary line maintenance permit.
ATV Trail	Township 54N, Range 7W, Section 10 Wyss	Verbal contact and sent a letter of violation. Notice was received. Barrier placed on ATV trail.
Mowing Project lands	Township 54N, Range 7W, Section 2 Fairchild	Sent letter of violation. Notice was received.
Mowing Project lands	Township 54N, Range 7W, Section 14 Burditt	Sent letter of violation. Notice was received. Landowner issued boundary line maintenance permit.
Mowing Project lands	Township 55N, Range 7W, Section 14 Reagan	Verbal contact and sent letter of violation.
Mowing Project lands	Township 55N Range 7W Section 14 Luetkemeyer	Letter of violation sent. Verbal contact.
ATV Trail	Township 55N, Range 7W, Section 5 Mihulka	Sent letter of violation. Notice was received. Verbal contact was made.
ATV Trail	Township 55N, Range 7W, Section 5 Pentland	Sent letter of violation. Notice was received.
Mowing Project lands and ATV Trail	Township 55N, Range 6W, Section 8 Cockrell	Sent letter of violation.. Notice was received. Verbal contact was made.

**Annual Boundary Report; Clarence Cannon Dam and Mark Twain Lake, FY15**

3. The following is a list of actions that occurred on flowage easement lands during FY 2015.

<b>ENCROACHMENT/ TRESPASS</b>	<b>ACTION TAKEN</b>
Tract 1838 E-1, T54N, R9W, Sec. 21, Pond Jim Riechmann, 18295 MCR 489, Stoutsville, MO 65283	Letter of violation sent on Nov. 4, 2015
Tract 2317 E-1, T54 N, R9W, Sec. 7, Wetland Carl and Kathy Willoughby, 2170 Woods Creek Road, Robertsville, Missouri 63072	Letter of violation sent on Nov. 4, 2015

4. The following is a list of monuments that have been identified as missing or displaced:

- T54N, R8W, Sec. 28—AP #3 missing one RM.
- T54N, R9W, Sec. 29---AP#10 missing.
- T54N, R9W, Sec. 8 – AP#3 will be displaced. Set new RMs.
- T53N, R8W, Sec. 4 – AP#7 displaced on slope.
- T53N, R8W, Sec. 17 – AP#1 displaced on slope.

5. FY 2016--- Maintenance and inspection of approximately 80 miles of perimeter boundary line, beginning at T54N, R9W, Sec. 9 and extending east to T55N, R8W, Sec 14, will be completed in FY 16. Project staff will perform all inspections and maintenance.